



SECOND FLOOR INSET



FIRST FLOOR



Hannah Ave

13th St

TITLE

ENVIRONMENTAL CONDITION
OF PROPERTY REPORT

Navy Reserve Center
Forest Park, IL

LEGEND

- Locations of Asbestos Containing Material (ACM)
- Lead-Based Paint
- Tested for Lead-Based Paint, none detected
- Hazardous Substances Locations
- Medical Waste Locations
- Buildings
- Site Boundary
- Major Road
- Local Road
- SF - Square Feet
- LF - Linear Feet

SITE LOCATION MAP



NOTES & SOURCES

Coordinate System: NAD 83, UTM Zone 16
Data Sources: Toltest 2000, 2001, 2003;
Navy 1997, 2003; TLI 2003



FIGURE

